




NOTES:

*1 - Some sensors require a load resistor, check with your manufacture.

PPO2.COM		Schematic diagram PPO2 board, #SS-PP02-1		
WWW.PPO2.COM	SIZE A	DWG. By: Mark Munro	DWG NO.: SS-PP02-1	REV 0
http:\\www.ppo2.com\\files\\	Date: 8/21/00	SHEET: 1 OF 1		